SAIGON BASE MONTHLY REPORT AUGUST 1969

- I. GENERAL
- 1. The overall activities during the past month were routine with the flying decreased slightly as forecasted. The forecast was within .2% of actual. Enemy activities have increased considerable and Saigon continued to receive rockets and terrorist activities which make living a little uncomfortable.
- The Saigon Retail Price Index remained rather stable from August 2. The Saigon Retail Frice limes remained above the April level. The rate of 1968 to April 1969, but is now 12% above the April level. The rate of increase has declined. The index for all items rose 7% in May, 4% in June and only 1% in July. The July increase was almost entirely attributable to the impact of the increased per equation tax.
- II. FACILITIES DEVELOPMENT 1. SFD Phil Doyle was transferred to Udorn leaving SCM the responsibilities of Facilities Development. There are two major projects underway. (1) The revetment fence along the northwest side of the area. (2) The water system. Both of these projects are approximately 90% completed. The new antenna masts and accessories are scheduled for arrival during September so we will start the final phase of relocating the transmitters toward the end of the month.
- III. OPERATIONS 1. Total revenue block time for August was 6128 + 34 compared to 6397 + 22 for July. Our revenue forecast for the month was nearly perfect as we predicted 6135 revenue hours. The Caribous flew 169 + 07 revenue hours which was a substantial increase over previous months.
- 2. One other TCN was transferred giving a total of 4 less TCN's and 3 Americans since we initiated our cost reduction program. PM/SGN has been advised to hire locals to fill the slots of TCNs. OM Macfarlane is cross-trained to cover OM and FIC shifts.
- 3. There were 18 controllable and 46 uncontrollable delays with a total of 907 Saigon departures. These figures are practically the same as the previous months.

FIC, GTD and the Emergency Equipment Room are in good order. Customer relations have remained good.

Flight Time Report (See attachment A)

Aircraft Incidents Report (See Attachment B)

IV. TRAFFIC/AAM

1. The SRTM position reportedly has again been transferred to Saigon. Although no written direction from management has been received I have continued to perform the functions during the reporting month.

A "Vector Control" program was instigated with a score of 5 KIA rodents for the month. This will be a continuous program with traps set during aircraft RONs.

2. The new Contract of Carriage forms were placed in use. Several problem areas have been noted and this will be discussed in a separate letter.

As mentioned in my SRTM/SVN/M/69/135 dated 20 August there have been some differences of opinion on baggage to be carried on our aircraft. We are attempting to conform to basic safety guidelines and still satisfy the Customer using the criteria outlined in BM memo BMSGN/69/285.

- 3. We have secured adequate storage in the Customer Warehouse and the covered area outside the warehouse for Company cargo. Although somewhat removed from our work area it has proven to be sufficient for our needs.
- 4. Checking of Beech seats by numbers with drawings indicated an error in seat numbers. We have received an engineering evaluation and have started to have the seats configured correctly.

			July	August	
Passengers departure # arrival Outbound cargo Inbound cargo	SGN SGN SGN SGN	(All contracts)	6021 6622 72793 89632	6731 57 69543 3 47	837 980 217 205

5. TRAFFIC/USAID

		Cargo (including AF Caribou A/C)	
		July August	. 312 312//
Outbound (lbs)	SGN	2,841,844 1,626,899	1, 369, 268 14
Inbound (lbs)	SGN	586,425 540,886	519,743

V. HOSTEL CCCUPANCY

1. During the month of August 1969, 3 beds out of 186 were utilized for a 1.6% occupancy rate. Also, there were no Non-Availability slips issued during the month.

VI. FLYING

1. The gravest problem confronting the Flying Department in many respects is lack of utilization of the VTB yet the schedule requires many hours of standby by the crews. This problem has been prevelant for some time. I do not think it will be with us too much longer as we will have no VTB crews to worry about. This standby problem is becoming so serious that, to date, four Captains have voiced a strong indication of resigning, and five Captains have vehemently requested transfer out of the VTB program. Such actions seem natural enough considering for every four hours of duty time, a VTB Captain receives only one hour for pay purposes.

To counteract these inequities:

- We have forwarded studies to the HM for discussion with the customer,
- We forwarded a study to the DFD for salary consideration regarding standby time,
- We have cross-trained personnel into the VTB but so far we have been unsuccessful in cross-training any personnel out, as every PIC trained-in are being utilized standing-by.

- 2. So far no assistance from the customer appears to be forthcoming, the DFD has not had time to act upon salary adjustment, and our cross-training program has reached a stand still, as far as getting volunteers to train into the program, and from an economical view point.
- 3. Morale in other programs is naturally very good. The flying time is up in all other programs and there were no accidents for the month.

VII. SAFETY

- 1. Pilot Meetings VTB 7 August
- a. Recent aircraft troubles, Saigon and out-station maintenance, maintenance write-ups, and wind, weather, and airfield hazards were discussed.
- b. Technical and printing errors in the new VTB Flight Manual were brought to the pilots' attention.
- C-46 11 August. Following items affecting flight safety were discussed:
- a. Use of non-standard cockpit signals. This practise will be discontinued and flight crews will be spot checked for compliance.
- b. It has been observed that many pilots are failing to use checklists installed in aircraft. Disciplinary action will be taken against further infractions of this rule.
- c. Taxing with hands hanging out of windows and not holding yoke was discussed.
- d. Removal of landing gear pins. After ≠2 has been started and the hydraulic pressure is up, the PIC will signal for removal of the gear pins prior to starting ≠1.

Beechcraft - 26 August. Following safety items were discussed:

- a. Caution about vehicular traffic on the new road which crosses the AAH taxiway.
- b. Pilots were informed to check for proper installation of forward and rearward facing seats. Seat failures in a recent accident may possibly have resulted from improper installations.
- c. Recently, a passenger in the copilot seat of a VTB grasped the control wheel during landing. Pilots were warned to thoroughly brief any passenger occupying this seat.
- d. A recent accident at another station revealed that some passengers aboard did not have sent belts available. Pilots were warned to assure that every occupant has available, and wears a seat belt. Exceptions should be made only in grave emergencies.
- e. Pilots were cautioned to check for accumulation of mud in wheel wells after operating on muddy surfaces. Excess mud in wheel wells can result in a gear-up landing.

204B - 30 August

- a. N1307X FCU malfunction of 27 August was reviewed. Pilots were advised of residual high EGT during emergency, and necessity for slow application of power after switching to manual fuel control. This emergency occurred at 1800' and approximately 500' was lost in entering autorotation, diagnosis of problem, and effecting manual control to recover.
- b. Pilots were reminded of necessity for complete, accurate write-ups whenever a malfunction occurs. This will enable MMB to diagnose malfunctions which in the past may have gone undetected.

2. Accident Investigations

- Investigation of Beech 10-2, N9521Z accident at V-05, Vung Tau on 26 July 1969 has been completed except for the report of analysis on landing gear and brake components. Anticipate completion of Local Board of Review prior to 15 September.
- b. Local Board of Review for VTB, N3674G accident was completed on 14 August and submitted to the Head Office.
- suffered the loss of a finger as a result c. Traffic utilityman of being caught in a lowering forklift boom at Danang on 29 August. Employee Accident Form PD-137R5 will be submitted.

VIII.

- 1. As was the case in July, activities were largely routine with the exception of the work done on the Vietnamese Line Maintenance Training Program and on Work Permits. Ministry of National Defense approval to leave the country has been granted to 22 of the primary Trainee candidates and to all 10 alternates. What remains is Directorate of Civil Aviation and Ministry of Education program sanction and approval. The Ministry of Labor advises that these approvals will be forthcoming shortly, and also that the candidates' passport and exit permit applications will be expeditiously handled.
- 2. Work Permit approvals continue to be a problem. The new application procedures are not moving along smoothly at all. Unfamiliarity with this new system together with the large amount of paperwork necessary for each application has resulted in confusion and mishandling at all stages in the procedure. We have our hands full with this further compounded by the government's attitude toward TCNs.
- recommended and instituted a follow-up procedure which, assuming cooperation from the application handling personnel, will enable us to maintain better control over the Work Permit applications. Heretofore we had depended on USAID for this control, but with little positive result. Hopefully with our direct control throughout all stages of the procedure we will be able to enjoy success.
- 4. Personnel Strength (See Attachment C)

IX. TECHNICAL SERVICES

- 1. August was a quiet month without any major crisis or serious incidents. Our cost reduction program continued with emphasis on personnel reductions. The goal we set for ourselves was \$90,000 a month reduction by 31 October 1969, and to date we have finalized plans for slightly over \$70,000 monthly, but our "goal" is a long way off. The manpower is approaching the balance point in respect to our current overall workload. RMD and GMD have shown the best results in tightening of the purse strings as related to cost (personnel) cuts. Da Nang and Nha Trang Technical Services Depts have also done very well in reductions of personnel.
- 2. The flying hours for August was about 6,327 total, which is the range we are trimming our manpower for. This was near the figures for June and July. One of our competitors (CASI) is supposedly pulling up stakes at the end of October and we are hopeful that some contract arrangements can be put together, so as to enable us to acquire most of their current flying contracts. At this point our chances are probably 50-50.
- 3. Our revetment (perimeter) wall along the northwest edge of our ramp is nearing completion. This wall is made of pre-cast reinforced panels that insert between poured columns. The wall extends from the USAID warehouse along N.W. ramp to the west end of the RMD ground equipment parking area near the tilities Building. Ramp lights are being mounted on poles on top of every fourth column, as part of the perimeter lighting A.R. project.
- 4. The newly concreted west ramp is now being fully occupied with aircraft. China Air Lines was assigned four parking spots (2 C46 & 2 C123), this permits us to park 2 DHC/4 and 6 C46/C47 aircraft. This has really helped to relieve most of the conjestion from the area in front of the USAID warehouse. Now if we can obtain funding for lighting, and electrical (power) system and some other utilities, the west ramp would be very good.
- 5. The RMD Ramp Crew was issued some "AAM SGN made" day-glo vests to identify themselves to flight crews and other associated functions. These vests are worn over their white uniforms. The orange (day-glo) and white color contrast gives them a very professional appearance as well as improving overall ramp safety,

X. FISCAL

1. Contract Billing

	Fly	ing Services	Others	
VN-41/cords	US\$797,109.35	VN\$1,052,879.00	US\$6,321.43	VN\$25,150
AN-71/EMB	174,429.16		6,420.87	
VN-41/RDC	24,876.03		231.05	
4395 (Sub. Cont	.) 96,877.13			•
00005	25,826.82		45.16	
00069	20,919.79			
Others			1,092.26	
Credit Note to	VN-41		(44.85)	

2. Total flying hours including CAL Sub-Contractor

Revenue Block time:	6,405+33
Flight Time:	5,542+33
Hazard Time:	4,408+42
Total log sheets processed:	1,617
Passengers:	41,993
Cargo:	3,073,754 lbs
Non-revenue block time	279+32
Flight Time	229+14

3. Payroll and Timekeeping

		Amount	No. of Person
payroll			776
TCN Plastres Allowance	VNS	2,658,015.00	477
American Piastres Allowance	VN3	1,036,590.00	175
Payroll	USS	78,244.57	202
Payroll	USS	7,776.97	30

DSL: 76,449 hrs.

Number of persons filling DTR: 368

4. Total disbursements: VN\$18,035,008.00 MPC 151.45

Free market rate: VN\$ 220 to US\$ 1.00

ORIGINAL SIENCED SE E. J. TABLESTO ABM - GGN

E.J. Theisen

SAIGON BASE FLIGHT TIME REPORT AUGUST 1969.

Contract 4101
N67985 162+36 134+11 1+40 0+59 B910 122+23 102+14 1+40 0+59 B928 66+03 54+53 22+4,3 19+57 B138 125+02 103+37 2+10 2+00 B146 40+43 31+57 3+06 2+41 6147 119+13 104+01 4+09 3+23 8084 127+20 109+17 5559 159+09 144+31 5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N99577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664G 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N76950 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 M9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N67985 162+36 134+11 1+40 0+59 B910 122+23 102+14 1+40 0+59 B928 66+03 54+53 22+4,3 19+57 B138 125+02 105+37 2+10 2+00 B146 40+43 31+57 3+06 2+41 6147 119+13 104+01 4+09 3+23 8084 127+20 109+17 5559 159+09 144+31 5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N99577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664G 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
B910 122+23 102+14 1+40 0+59 B928 66+03 54+53 22+43 19+57 B138 125+02 103+37 2+10 2+00 B146 40+43 31+57 3+06 2+41 6147 119+13 104+01 4+09 3+23 8084 127+20 109+17 55559 159+09 144+31 5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N77Y 116+14 97+14 4+27 3+33
B928 66+03 54+53 22+43 19+57 ## B138 125+02 103+37 2+10 2+00 ## B146 40+43 31+57 3+06 2+41 ## 6147 119+13 104+01 4+09 3+23 ## 8084 127+20 109+17 ## 5559 159+09 144+31 ## 55994 88+26 74+17 ## 8817 42+15 36+02 4+53 3+31 ## 8829 78+08 59+18 12+09 10+19 ## 6083 113+12 94+31 ## 15397 52+50 43+49 23+48 21+38 ## 15447 4+02 3+04 ## 19518Z 83+28 71+47 3+21 2+02 ## 10418 104-37 34+41 5+40 2+47 ## 10418 104-37 34+41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 104-37 34-41 5+40 2+47 ## 10418 10418 10418 10418 10418 ## 10418 10418 10418 10418 ## 10418 10418 10418 10418 ## 10418 10418
B138 125+02 103+37 2+10 2+00 B146 40+43 31+57 3+06 2+41 6147 119+13 104+01 4+09 3+23 8084 127+20 109+17 5559 159+09 144+31 5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3654V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N77Y 116+14 97+14 4+27 3+33
B146
6147 119+13 104+01 4+09 3+23 8084 127+20 109+17 5559 159+09 144+31 5994 88+26 74+17 8817 42+15 36+02 4+53 3+31 8829 78+08 59+18 12+09 10+19 6083 113+12 94+31 8539Y 52+50 43+49 23+48 21+38 8544X 4+02 3+04 89518Z 83+28 71+47 3+21 2+02 86154U 40+37 34+41 5+40 2+47 89956Z 31+15 26+34 1+26 0+51 87770B 95+45 82+30 3+43 2+57 89958Z 24+51 21+19 1+50 1+26 83728G 64+12 55+38 0+49 0+23 89664G 9+30 7+29 3+33 2+06 83674G 20+11 18+33 87695C 76+02 65+37 1+46 0+51 87573Z 97+39 82+57 5+06 4+25 8777Y 116+14 97+14 4+27 3+33
8084 127+20 109+17 5559 159+09 144+31 5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
5559 15940 88426 74+17 B817 42+15 36+02 47+18 12+09 10+19 6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 19838Z 24+51 21+19 1+50 1+26 13728G 64+12 55+38 0+49 0+23 19664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
5994 88+26 74+17 B817 42+15 36+02 4+53 3+31 B829 78+08 59+18 12+09 10+19 6083 113+12 94+31 12+09 10+19 8083 113+12 94+31 12+09 10+19 8083 113+12 94+31 12+09 10+19 8083 113+12 94+31 12+09 12+38 8095447 44-02 3+44 14-02 3+04 809518Z 83+28 71+47 3+21 2+02 8015440 40+37 34+41 5+40 2+47 80956Z 31+15 26+34 1+26 0+51 80957Z 70+43 60+55 2+58 2+24 80957Z 70+43 60+55 2+58 2+24 80958Z 24+51 21+19 1+50 1+26 809728G 64+12 55+38 0+49 0+23 8095644C 9+30 7+29 3+33 2+06 809573C 76+02 65+37 1+46 <t< td=""></t<>
B817
B829 78+08 59+18 12+09 10+19
6083 113+12 94+31 N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N539Y 52+50 43+49 23+48 21+38 N544Y 4+02 3+04 N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N544Y N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N9518Z 83+28 71+47 3+21 2+02 N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N54,54V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N6154U 40+37 34+41 5+40 2+47 N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 0+55 N5269V 117+34 100+02 17+14 4+27 3+33
N9956Z 31+15 26+34 1+26 0+51 N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N7770B 95+45 82+30 3+43 2+57 N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N771 116+14 97+14 4+27 3+33
N9577Z 70+43 60+55 2+58 2+24 N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N9838Z 24+51 21+19 1+50 1+26 N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N3728G 64+12 55+38 0+49 0+23 N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N9664C 9+30 7+29 3+33 2+06 N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N3674G 20+11 18+33 N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N7695C 76+02 65+37 1+46 0+51 N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N5454V 19+06 14+45 1+14 0+55 N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N6622C 15+33 11+14 N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N9573Z 97+39 82+57 5+06 4+25 N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N5269V 117+34 100+02 N77Y 116+14 97+14 4+27 3+33
N77Y 116+14 97+14 4+27 3+33
N51259 14+21 11+34 21+44 19+04
N21412 37+19 30+08 3+15 2+30
N9073Z 3+44 2+55 11+36 8+05
N9871Z 4+28 4+00 %+30 1+00
N9898Z 5+20 4+28
N358F 130+40 111+43 2+22 1+24
N285L 189+02 154+52 3+49 3+20
N391R 146+54 120+09 3+27 1+50
N394R 159+45 132+58 5+46 4+55
N9444 133+32 115+49 4+45 3+20
N198X 152+59 126+39 7+20 5+52
N153L 142+52 128+08 5+11 4+05
N180K 115+34 102+00 0+42 0+25

	N12450 N748N N1521 N1841 N185K N192X N393R N1303X N1304X N1305X N1306X N1307X N8512F N8513F N8535F	44+02 10+46 6+27 23+56 37+42 99+49 32+56 30+04 159+08 106+32 135+23 101+34 193+09 24+14 8+18 34+22	39+04 9+27 5+47 19+56 32+05 86+43 29+21 27+26 159+08 106+32 135+23 101+34 193+09 24+14 8+18 34+22	1+45 3+35 7 +15 3+40 2+25	1+45 3+35 7+15 9 +40 2+25
	Sub-total	4571+34	3989+35	238+41	196+18
2. Contract	4102				141
	5994	17+26	15+03		
	5559	6+17	5+47		
	N539Y	3+20	2+06		
	N544Y	31+03 77+33	25+33 45+33		
	N3674G N7695C	77+11 15+09	65+11 13+02	1	
	N91295	64+11	55+28	3+22	2+31
	N7770B	2+11	2+00	,	
	N3728G	4+05	3+19		
54	N748N	76 +37	68+52	5+55	4+58
	N152L	128+11	113+01	9+47	8+02
	N184L	72+23	58+28 50+35	5+45	4+14
	N185K	56+57 20+32	50+15 17+24	2+14	1+19
	N192X N393R	46+18	41+13	2+19	1+35
	N194X	85+40	71+27	2+07	1+35
	N9073Z	1+00	0+44		
•	N285L	1+13	0+43		
	N391R	2+25	1+55		
	N394R	3+03	2+32		
	N198X	11+21	10+24		
	N180K	9 +35	8+46	6+10	ELDE
	N12450	97+11 22+19	87+15 22+19	2+30	5+35 2+30
	N8513F N8512F	12+32	12+32	4+27	4+27
	EN JAME	بنازا نامد	400	~ . ~ (4.21

S. B. S. S. S.

		N8514F N8535F N1303X N1304X N1305X N1307X	82+42 55+32 21+22 3+14 1+58 2+33	82+42 55+32 21+22 3+14 1+58 2+33	1+00 3+35 49+11	1+00 3+35
3.	Contract 4	103				
		N67985 B910 B928 B138 B146 5994 B829 6083 N539Y N544Y N9577Z N5454V N6622C N9573Z N5269V N77Y N7950C N51259 N21412 N9898Z N358F N2851 N180K N1306X N1306X N1306X N1307X N8512F N8513F N8535F	3+40 18+16 43+44 21+23 15+14 6+19 75+16 26+38 14+35 14+35 14+35 14+30 14+35 14+30 14+35 14+30 14+31 14+30 14+31 14	1+40 15+05 37+28 16+47 13+13 5+25 4+55 6+07 22+19 2+35 10+22 3+32 6+48 7+0a 1+36 10+50 3+10 3+10 3+19 0+50 3+10 17+39 32+31 16+10		

4.	Contract 0005	-				
		n6622C N5454V N9573Z N51259	27+55 3+40 10+58 4+45	23+38 3+26 10+13 3+54	1+49	1+05
		Sub-total	47+18	41+11	1+49	1+05
5.	Contract 0069	N9664C N9518Z N3728G N7770B N91295 N9838Z	46+54 16+32 7+25 4+20 2+34 10+17	41+15 14+32 6+31 4+02 2+13 9+10	3+03	2+05
		Sub-total	88+02	77+43	3+03	2+05
		Total Non-Re	ne Block Time ne Flight Time evenue Block ! evenue Flight	Time	6128+34 5357+54 292+44 240+49	
		GRAND TOTAL	BLOCK TIME FLIGHT TIME		6421+09 559 8+4 3	

	Flight	Time by Type of	Aircraft	
	Rev	enue	Non-Re	venne
Type of A/C	Block time	Plight Time	Block time	Flight Time
C-46	649+36	536+42	58+20	50+45
C-47	126+42	100+15	17+02	13+50
Bailed C-47	645+01	558+55	4+09	3+23
DHC-4	169+07	139+54	27+50	24+42
VIB	770+29	664+21	31+31	20+23
10-2 (Beech)	617+00	505+12	37+35	31+32
C-45	10+23	8+28	18+26	13+33
Porter	2079+02	1782+51	67+39	52+29
204B	1061+15	1061+15	30+12	30+12
TOTAL	6128+34	5357+54	292+44	240+49

Original Signed By L.G. PARRISH L.G. Parrish

ATTHEHMENT "A"

- Flight Onformation Tenter - saigon-

MONTHLY ACTIVITY REPORT 1-31 AUGUST 1969.

ART I - AIRGRAFT INCIDENTS -

Date	: A/C No., Type 4 Contract	: Place	: Description
ll Aug.	: N1307X : D0A-8 : 13091	: Between : V-246 & : 30 3210	: While moving sling loads between V245 : & RT3210 acft received one hit thru : the belly striking a main epar. No : personnel injuries.
17 Aug.	: N1305X : 204-B : 4101	1 15 67£4 1	: Acft sustained three hits in rotor : blade tip, while circling villags : at customer direction. No personnel : injuries.
17 Aug.	#853.52 204-8 4100	: Soccer : Field at : V-23	: While on ground, one round of unknown : caliber rocket fire impacted on S.E. : portion of field. No acft damage or : personnel injuries occurred.
18 Aug.	#1303X 204-8 4101	: BT 3108	: After touchdown at IZ, O3X received : aniper fire, which impacted in front : of aeft. so acft damage or personnel : injuries occurred.
27 Aug.	N539Y N539Y N539Y N539Y N539Y	: Landing : V-20	: The left inboard main tire ree'd one : round of groundfire while landing at : VAO. Lamage repair completed at V17. : Eo personnel injuries involved.
28 Aug.	* N1305X * 204-8 * 43-01	: NE of : 5-149 :	Acit was flying below weather when PII observed four flashes from ground three being directed at 05%. Fig applied max power and executed immediate elimbout. Acit continued wiseign without further incident. We acit demage or personnel injuries involved

- SITUATION SUPPLARY -

Few major attacks occurred during August, however many scattered and separate incidents took place. DANANG AB received a LACMM rocket attack. CAM RANH BAY received both rocket and sapper attacks including attacks on the 6th Convalescent Hospital with plastic charges. Many base camps and fire support bases in III Corp received scattered rocket and mortar attacks. In SAIGON a USAF Language School in front of the Dong-Whanh Hotel was sabatoged with a sixty pound plastic charge, killing eight and wounding sixty-two. During this period SAIGON received rockets in the cock area and terrorist remained active with several grenade incidents reported. Significant enemy buildup occurred in parts of IV Corp with several major population centers including CAN-THO, receiving rocket and mortar attacks. For the present time enemy activity is expected to remain at a moderate isvel. Emphasis is expected to remain on small unit action. Attacks by fire, samper actions, and ground probes against small units anstallations is expected to continue.

E. J. WILSON

Distribution:

VPFO/TPE (2) BM/SCN (3) SOM/SON (1) FIG/File.(1)

ATTACHMENT "B"

	2.5						_		,			R	August	31 August 1909	6				
		1		+	į-		-									-			
					-											þ	TOTAL	AL	
																			Ε
CLASSIFICATION	GRD FLT	FLT	GRD FLT GRD FLT	FLT	(F3D)	FLT	GRD	FLT	CHO	GRD FLT GRD FLT		GRD FLT	GRD FLT		GRD FLT	FLT	OHS	17.1	_
		1		-						**	- 2		1		*		1	,	ţ
PERMANENT	\$	44 154 150	150	2	197		23		8	5 569" 15"	<u>س</u>		CA		H		X) ST	
		1		†							L								
TEMPORARY											\perp								
7 mar																			
) 											ŀ								
																	•		
PRE-PROCESSED	~								E								4		:
									_										
								¥	6	4 2 Kerry 3 2	\$		~		*~		926	a	167
TOTAL	£5.	がい	45 154 150	- 1	Tor Ex		9	^	216	3	- 1				1				• •
			:																

A SI 国

SAIGON

9% 184 GROUND PNL : FLIGHT PNL :

TOTAL :

DAMANG PUR-B ALLE

31 August 1969

									TOTAL	I.
CLASSIFICATION	GRD	FLT	GAD FLT	FLT	GRD	FLT	GRD	FLT	GRD	FLT
PERMANENT	4		4		a		83		ES	
TEMPORARY		,					·	_		
C E E										
TOTAL PRE-PROCESSED	4		*		ន		2		8	
TOTAL										

330 PNL : 133

FLIGHT PNL :

TOTAL : 133

MHA THANKI SUD-BASE

						-				
									TOTAL	1
CLASSIFICATION	GRD	FLT	GAD	FLT	GRD	FLT	GRD	FLT	CRD	FLT
PEZMÁNENT	•		2		25		29		97	
	^		3							
TEMPORARY										
FTC										
			-							
PRE-PROCESSED						-				
TOTAL	~		15		25		65		orr	
Martin Co. Company of the second contract of										

SHOWND PML: 110

OLL : TOTAL

CAN THO SUB-BASE

31 August 1969

CLASSIFICATION GRD FLT LT LT						-		-	E	,
GRD FLT GRD FLT GRD FLT GRD 10									TOTA	
30 4	CLASSIFICATION	GRD		GKD	FLT	GRD	FLT	GRD	GRD	FLT
SSEU LO LA	מישורים ביינים ב		i							
SSE/I)	PREMA NEMP					9		4	22	
OCESSED 10 4	The state of the s	•								
COCESSED 10 4	Ve A doct-warm									
COCESSED 10 4	THATOURANT	-								
COCESSED 10 4	c C E									
OCESSED 10 4	FIC									
10000000	(TAT O SEED OF CH. T. F.									
10 4	PRE-PROGESSIA									
	1 4 H C H					2		4	13	
	TAIOI	-								

3.40 UND PNL:

FLIGHT PNL:

: TYLOL